

## **PATENT**

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)
MASAAKI SUZUKI	: Examiner: A. Markoff )
Appln. No.: 10/828,347	: Group Art Unit: 1746
Filed: April 21, 2004	: Patent No.: US 6,946,035 B2
•	: Issued: September 20, 2005
For: METHOD OF CLEANING SUBSTRATE	) : June 22, 2006
	Certificat
Commissioner for Patents	Certificate  JUN 2 6 2006
P.O. Box 1450	of Correction
Alexandria, VA 22313-1450	00007

## REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 322

Sir:

Alexandria, VA 22313-1450

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Although no fees are believed to be necessary, any fees deemed necessitated by this paper may be charged to Deposit Account No. 06-1205. A duplicate copy of this paper is enclosed.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Mark A. Williamson Attorney-for Patentees Registration No. 33,628

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

MAW/llp

DC\_MAIN 224619v1

# Stable Here STRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

**CERTIFICATE OF CORRECTION** 

PATENT NO.

US 6,946,035 B2

DATED

September 20, 2005

INVENTOR(S) :

Suzuki

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### **COLUMN 4**

Line 36, "in here" should read --in the case where--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30) MAW/IIp DC\_MAIN

PATENT NO. <u>US 6,946,035 B2</u>

No. of add'l. copies @ 30¢ per page

JUN 26 ZUU6

# UNITED STATES PATENT AND TRADEMARK OFFICE

# CERTIFICATE OF CORRECTION

PATENT NO. :

US 6,946,035 B2

DATED

September 20, 2005

INVENTOR(S) :

Suzuki

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## **COLUMN 4**

Line 36, "in here" should read --in the case where--.

**MAILING ADDRESS OF SENDER:** 

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30) MAW/IIp DC\_MAIN

PATENT NO. <u>US 6,946,035 B2</u>

No. of add'l. copies @ 30¢ per page

